

Prepared For Exclusive Use By:

Mrs. Shannan Homebuyer  
Mr. Wesley Homebuyer

Property Address:

1600 Pennsylvania Ave  
Prairieville LA 70769



Pro2Call Property Evaluations LLC dba HouseMaster

Inspector: Mike Jordan

Office:225-673-2441 Cell:225-773-6263 [www.tigertown.housemaster.com](http://www.tigertown.housemaster.com)

Inspection Date: 10/10/2008

**INSPECTION INFORMATION**

**CLIENT:**

Mrs. Shannan Homebuyer  
Mr. Wesley Homebuyer

**PROPERTY ADDRESS:**

1600 Pennsylvania Ave  
Prairieville LA 70769

**INSPECTION DATE/TIME:**

10/10/2008 - 09:00 AM

**INSPECTOR:**

Mike Jordan

**INSPECTION COMPANY:**

Pro2Call Property Evaluations LLC dba HouseMaster  
Office:225-673-2441 Cell:225-773-6263  
www.tigertown.housemaster.com

**INSPECTION DETAILS**

**DESCRIPTION:**

Single Family

**AGE OF HOME:**

7 to 8 years

**TYPE OF INSPECTION:**

Standard Home Inspection

**STATUS OF HOME:**

Occupied

**WEATHER:**

Sunny

**PEOPLE PRESENT:**

Buyer, Buyer and Seller Agents

**TEMPERATURE:**

80 F

**AUTHORIZED DISTRIBUTION:**

Client and Client's Agent

**INTRODUCTION**

The purpose of this report is to render the inspector's professional opinion of the condition of the inspected elements of the referenced property (dwelling or house) on the date of inspection. Such opinions are rendered based on the findings of a standard limited time/scope home inspection performed according to the Terms and Conditions of the Inspection Order Agreement and in a manner consistent with applicable home inspection industry standards.

The inspection was limited to the specified, readily visible and accessible installed major structural, mechanical and electrical elements (systems and components) of the house. The inspection does not represent a technically exhaustive evaluation and does not include any engineering, geological, design, environmental, biological, health-related or code compliance evaluations of the house or property. Furthermore, no representations are made with respect to any concealed, latent or future conditions.

The GENERAL INSPECTION LIMITATIONS on the following page provides information regarding home inspections, including various limitations and exclusions, as well as some specific information related to this property.

The information contained in this report was prepared exclusively for the named Clients and is not transferable without the expressed consent of the Company. The report, including all Addenda, should be reviewed in its entirety.

**REPORT TERMINOLOGY**

The following terminology may be used to report conditions observed during the inspection. Additional terms may also be used in the report:

**SATISFACTORY** - Element was functional at the time of inspection. Element was in working or operating order and its condition was at least sufficient for its minimum required function, although routine maintenance may be needed.

**FAIR** - Element was functional at time of inspection but has a probability of requiring repair, replacement or other remedial work at any time due to its age, condition, lack of maintenance or other factors. Have element regularly evaluated and anticipate the need to take action.

**POOR** - Element requires immediate repair, replacement, or other remedial work, or requires evaluation and/or servicing by a qualified specialist.

**NOT APPLICABLE** - All or individual listed elements were not present, were not observed, were outside the scope of the inspection, and/or were not inspected due to other factors, stated or otherwise.

**NOT INSPECTED (NOT RATED)** - Element was disconnected or de-energized, was not readily visible or accessible, presented unusual or unsafe conditions for inspection, was outside scope of the inspection, and/or was not inspected due to other factors, stated or otherwise. **Independent inspection(s) may be required to evaluate element conditions.** If any condition limited accessibility or otherwise impeded completion of aspects of the inspection, including those listed under LIMITATIONS, it is recommended that limiting factors be removed or eliminated and that an inspection of these elements be arranged and completed prior to closing.

**IMPORTANT NOTE:** All repair needs or recommendations for further evaluation should be addressed prior to closing. It is the client's responsibility to perform a final inspection to determine the conditions of the dwelling and property at the time of closing. If any decision about the property or its purchase would be affected by any condition or the cost of any required or discretionary remedial work, further evaluation and/or contractor cost quotes should be obtained prior to making any such decisions.

## NATURE OF THE FRANCHISE RELATIONSHIP

The Inspection Company ("Company") providing this inspection report is a franchisee of DBR Franchising, LLC ("Franchisor"). As a franchisee, the Company is an independently owned and operated business that has a license to use the HouseMaster names, marks, and certain methods. In retaining the Company to perform inspection services, the Client acknowledges that Franchisor does not control this Company's day-to-day activities, is not involved in performing inspections or other services provided by the Company, and is in no way responsible for the Company's actions. Questions on any issues or concerns should be directed to the listed Company.

## GENERAL INSPECTION LIMITATIONS

**CONSTRUCTION REGULATIONS** - Building codes and construction standards vary regionally. A standard home inspection **does not include** evaluation of a property for compliance with building or health codes, zoning regulations or other local codes or ordinances. No assessments are made regarding acceptability or approval of any element or component by any agency, or compliance with any specific code or standard. Codes are revised on a periodic basis; consequently, existing structures generally do not meet current code standards, nor is such compliance usually required. Any questions regarding code compliance should be addressed to the appropriate local officials.

**HOME MAINTENANCE** - All homes require regular and preventive maintenance to maximize the economic life spans of elements and to minimize unanticipated repair or replacement needs. Annual maintenance costs may run 1 to 3% (or more) of the sales price of a house depending on age, design, and/or the degree of prior maintenance. Every homeowner should develop a preventive maintenance program and budget for normal maintenance and unexpected repair expenses. Remedial work should be performed by a specialist in the appropriate field following local requirements and best practices.

**ENVIRONMENTAL AND MOLD ISSUES (AND EXCLUSIONS)** - The potential health effects from exposure to many elements found in building materials or in the air, soil, water in and/or around any house are varied. A home inspection **does not include** the detection, identification or analysis of any such element or related concerns such as, but not limited to, mold, allergens, radon, formaldehyde, asbestos, lead, electromagnetic fields, carbon monoxide, insecticides, refrigerants, and fuel oils. Furthermore, no evaluations are performed to determine the effectiveness of any system designed to prevent or remove any elements (e.g., water filters or radon mitigation). An environmental health specialist should be contacted for evaluation of any potential health or environmental concerns. Review additional information on MOLD/MICROBIAL ELEMENTS below.

**AESTHETIC CONSIDERATIONS** - A standard building inspection does not include a determination of all potential concerns or conditions that may be present or occur in the future **including** aesthetic/cosmetic considerations or issues (appearances, surface flaws, finishes, furnishings, odors, etc.).

**DESIGN AND ADEQUACY ISSUES** - A standard home inspection **does not include** any element design or adequacy evaluations including seismic or high-wind concerns, soil bearing, energy efficiencies, or energy conservation measures. It also does not address in any way the function or suitability of floor plans or other design features. Furthermore, no determinations are made regarding product defects notices, safety recalls, or other similar manufacturer or public/private agency warnings related to any material or element that may be present in any house or on any property.

**ESTIMATED AGES** - Any age estimations represent the inspector's opinion as to the approximate age, and **are provided for general guidance purposes only**. Estimations may be based on numerous factors including, but not limited to, appearance and owner comment. Obtain independent verification if knowledge of the specific age of any element is desired or required. Age estimates are given in "years" unless noted.

**DESIGN LIFE RANGE** - These figures represent the typical economic service life range (in years) for elements of similar design, quality and type, as measured from the time of original construction or installation. Any stated **design life is presented solely as a guide**. It does not take into consideration abnormal, unknown, or discretionary factors, and is not a prediction of future service life.

**ELEMENT DESCRIPTIONS** - Any descriptions or representations of element material, type, design, size, dimensions, etc., are based primarily on visual observation of inspected or representative components. Owner comment, element labeling, listing data, and rudimentary measurements may also be considered in an effort to describe an element. However, there is no guarantee of the accuracy of any material or product descriptions listed in this report; other or additional materials may be present. Independent evaluations and/or testing should be arranged if verification of any element's makeup, design, or dimension is needed. Any questions arising from the use of any particular terminology or nomenclature in this report **should be addressed prior to closing**.

**REMEDIAL WORK** - Quotes should be obtained prior to closing from qualified (knowledgeable and licensed as required) specialists/contractors to determine actual repair/replacement costs for any element or condition requiring attention. Any cost estimates provided with a home inspection, whether oral or written, only represent an approximation of possible costs. Cost estimates do not reflect all possible remedial needs or costs for the property; latent concerns or consequential damage may exist. **If the need for remedial work develops or is uncovered after the inspection, prior to performing any repairs contact the Inspection Company** to arrange a re-inspection to assess conditions. Aside from basic maintenance suitable for the average homeowner, all repairs or other remedial work should be performed by a specialist in the appropriate field following local requirements and best practices.

**SELLER DISCLOSURE** - This report is **not a substitute for Seller Disclosure**. A Property History Questionnaire form may be provided with this report to help obtain background information on the property in the event a full Seller Disclosure form is not available. The buyer

should review this form and/or the Seller Disclosure with the owner prior to closing for clarification or resolution of any questionable items. A final buyer inspection of the house (prior to or at the time of closing) is also recommended.

**WOOD-DESTROYING INSECTS/ORGANISMS** - In areas subject to wood-destroying insect activity, it is advisable to obtain a current wood-destroying insect and organism report on the property from a qualified specialist, whether or not it is required by a lender. A standard home inspection **does not include** evaluation of the nature or status of any insect infestation, treatment, or hidden damage, nor does it cover issues related to other house pests or nuisances or subsequent damage.

**ELEMENTS NOT INSPECTED** - Any element or component not evaluated as part of this inspection should be inspected prior to closing. Either make arrangements with the appropriate tradesman or contact the Inspection Company to arrange an inspection when all elements are ready for inspection.

**HOUSE ORIENTATION** - Location descriptions/references are provided for general guidance only and represent orientations based on a view facing the front of the house from the outside. Any references using compass bearings are only approximations. If there are any questions, obtain clarification prior to closing.

**CONDOMINIUMS** - The Inspection of condominium/cooperative do not include exteriors/ typical common elements, unless otherwise noted. Contact the association/management for information on common element conditions, deeds, and maintenance responsibilities.

## **MOLD AND MICROBIAL ELEMENTS / EXCLUSIONS**

The purpose and scope of a standard home inspection **does not include** the detection, identification or assessment of fungi and other biological contaminants, such as molds, mildew, wood-destroying fungi (decay), bacteria, viruses, pollens, animal dander, pet or vermin excretions, dust mites and other insects. These elements contain/carry microbial particles that can be allergenic, infectious or toxic to humans, especially individuals with asthma and other respiratory conditions or sensitivity to chemical or biological contaminants. Wood-destroying fungi, some molds, and other contaminants can also cause property damage. One particular biological contamination concern is mold. Molds are present everywhere. Any type of water leakage, moisture condition or moisture-related damage that exists over a period of time can lead to the growth of potentially harmful mold(s). The longer the condition(s) exists, the greater the probability of mold growth. There are many different types of molds; most molds do not create a health hazard, but others are toxic.

Indoor mold represents the greatest concern as it can affect air quality and the health of individuals exposed to it. Mold can be found in almost all homes. Factors such as the type of construction materials and methods, occupant lifestyles, and the amount of attention given to house maintenance also contribute to the potential for molds. Indoor mold contamination begins when spores produced by mold spread by air movement or other means to an area conducive to mold growth. Mold spores can be found in the air, carpeting, insulation, walls and ceilings of all buildings. But mold spores only develop into an active mold growth when exposed to moisture. The sources of moisture in a house are numerous and include water leakage or seepage from plumbing fixtures, appliances, roof openings, construction defects (e.g., EIFS wall coverings or missing flashing) and natural catastrophes like floods or hurricanes. Excessive humidity or condensation caused by faulty fuel-burning equipment, improper venting systems, and/or inadequate ventilation provisions are other sources of indoor moisture. By controlling leakage, humidity and indoor air quality, the potential for mold contamination can be reduced. To prevent the spread of mold, immediate remediation of any water leakage or moisture problems is critical. For information on mold testing or assessments, contact a qualified mold specialist.

**Neither the evaluation of the presence or potential for mold growth, nor the identification of specific molds and their effects, fall within the scope of a standard home inspection. Accordingly, the Inspection Company assumes no responsibility or liability related to the discovery or presence of any molds, their removal, or the consequences whether property or health-related.**

## **ADDITIONAL COMMENTS**

## 1. ROOFING

The inspection of roofs and rooftop elements is limited to readily visible and accessible elements as listed herein; elements and areas concealed from view for any reason cannot be inspected. This inspection does not include chimney flues and flue liners, or ancillary components or systems such as lightning protection, solar panels, and similar elements, unless specifically stated. **Element descriptions are provided for general information purposes only; the verification of roofing materials, roof age, and/or compliance with manufacturer installation requirements is not within the scope of a standard home inspection.** Issues related to roof or roofing conditions may also be covered under other headings in this report, including the ATTIC section.

**ROOF STYLE:**

Mixed Slope  
Steep Slope

**MATERIAL:**

Composition Shingles

**ESTIMATED AGE:**

8 to 10 Years

**DESIGN LIFE:**

15 to 20 years

**INSPECTION METHOD:**

Ladder at Eaves  
Walked On

**CHIMNEYS/VENTS:**

Metal Chimney w/ Enclosure  
Metal Vents

**SPECIAL LIMITATIONS:**

Height and Design

S F P NA NI

					•				1.0 <b>ROOF COVERING</b>  The roof conditions observed might be indicative of roof wear, hail or storm damage, manufacturing defects, and/or other conditions. Home owner advises they are awaiting storm damage insurance claim and roof will be replaced before closing. Follow up and verify reroofing was complete before closing. Obtain copies of receipts and warranties.
					•				1.1 <b>EXPOSED FLASHING</b> Damaged flashing observed in several areas. Verify flashing deficiencies are corrected with roof replacement as indicated in the Roof Covering comments.
					•				1.2 <b>PLUMBING STACKS</b> Poor seal noted around plumbing vent stack at rear of home verify replacement with roof replacement. See comments in roofing section.
					•				1.3 <b>VENTILATION COVERS</b> Dryer exhaust vent terminates on rear roof. The vent has heavy lint accumulation. Verify cleaning or replacement with roof replacement. See comments in roofing section/
					•				1.4 <b>RAIN GUTTERS / EAVESTROUGHS</b> No gutters are present at the small alcove in the front of the house. (see comments in Site Elements) This is contributing to water ponding. It is recommended gutters be installed here. Home owner indicates gutters will be replaced at site of roof damage (see comment in Roof Covering) with roof replacement. Verify before closing.
					•				1.5 <b>DOWNSPOUTS / ROOF DRAINS</b>
									1.6 <b>FASCIA / SOFFITS</b> Soft/fascia damaged sheathing noted at along edge of roof; home owner indicates this will be replaced during reroofing. (see Roof Covering comments) Verify work completion before closing.
					•				1.7 <b>CHIMNEY</b>

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



1.0 ROOF COVERING Picture 1



1.0 ROOF COVERING Picture 2



1.1 EXPOSED FLASHING Picture 1



1.6 FASCIA / SOFFITS Picture 1

**NOTE:** All roofs have a finite life and will require replacement at some point. In the interim, the seals at all roof penetrations and flashings, and the watertightness of rooftop elements, should be checked periodically and repaired or maintained as required. Any roof defect can result in leakage, mold, and subsequent damage. Conditions such as hail damage or manufacturing defects or whether the proper nailing methods or underlayment were used are not readily detectible during a home inspection. Gutters (eavestroughs) and downspouts (leaders) will require regular cleaning and maintenance. All chimneys and vents should be checked periodically. In general, fascia and soffit areas are not readily accessible for inspection; these components are prone to decay, insect, and pest damage, particularly with roof or gutter leakage. If any roof deficiencies are reported, a qualified roofer or the appropriate specialist should be contacted to determine what remedial action is required. If the roof inspection was restricted or limited due to roof height, weather conditions, or other factors, arrangements should be made to have the roof inspected by a qualified roofer, particularly if the roofing is older or its age is unknown.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Gutters/Downspouts** - Unless otherwise noted, the assessment of gutter and downspout conditions is limited to their physical/material condition. The adequacy of water flow under normal rainfall or storm conditions cannot be determined during a limited time visual inspection. All gutters and downspouts must be checked and cleaned on a regular basis; any buildup or blockage, including that in underground lines can lead to overflow, leakage, and other detrimental conditions that could result in water intrusion or otherwise affect the structure or foundation.

**Gutter Option** - The need for gutters and downspouts (leaders) will vary with house/roof design, locale and surface drainage conditions. If present, regular checks and cleaning are advised. If not present, consider the benefits to be gained from proper control of roof run-off and diversion away from foundation.

**Roofer Opinion** - Obtain the roof manufacturer's and/or a qualified roofer's opinions as to roof conditions and, if necessary, remedial needs and associated costs, prior to closing. If overall roof wear or damage exists, replacement is normally required. In other cases, recommendations for roof replacement versus repair needs can be subjective and based on economic issues or discretionary issues.

**2. EXTERIOR ELEMENTS**

Inspection of exterior elements is limited to readily visible and accessible surfaces of the house envelope and connected appurtenances as listed herein; **elements concealed from view by any means cannot be inspected.** All exterior elements are subject to the effects of long-term exposure and sudden damage from ongoing and ever-changing weather conditions. Style and material descriptions are based on predominant/representative components and are provided for general information purposes only; specific types and/or material make-up material is not verified. Neither the efficiency nor integrity of insulated window units can be determined. Furthermore, the presence/condition of accessories such as storms, screens, shutters, locks and other attachments or decorative items is not included, unless specifically noted. Additional information on exterior elements, particularly windows/doors and the foundation may be provided under other headings in this report, including the INTERIOR and FOUNDATION/SUBSTRUCTURE sections.

**SIDING:**

Multiple Styles/Materials  
Hardboard/Fiberboard  
Brick Veneer  
Stucco

**PORCHES/DECKS:**

Covered Porch w/ Concrete Floor  
Front of House

**SPECIAL LIMITATIONS:**

Foundation Plantings

**S F P NA NI**

•					2.0 SIDING
•					2.1 WINDOWS
	•				2.2 ENTRY DOORS Main entry door has paint bubbles on the interior. This may be cosmetic but also shows signs of possible water penetration. Sand and repaint to avoid wood rot or insect infestation.
•					2.3 PORCH(ES)
•					2.4 ELECTRIC / GFCI
•					2.5 EXTERIOR FAUCET(S)

**S F P NA NI**

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



2.2 ENTRY DOORS Picture 1

**NOTE:** All surfaces of the envelope of the house should be inspected at least semi-annually, and maintained as needed. Any exterior element defect can result in leakage and/or subsequent damage. Exterior wood elements and wood composites are particularly susceptible to water-related damage, including decay, insect infestation, and mold. The use of proper treated lumber or alternative products may help minimize these concerns, but will not eliminate them altogether. While some areas of decay or damage may be reported, additional areas of concern may exist, subsequently develop, or be discovered during repair or maintenance work. Should you wish advice on any new or uncovered area of deterioration, please contact the Inspection Company. Periodic caulking/resealing of all gaps and joints will be required. Insulated window/door units are subject to seal failure, which could ultimately

affect the transparency and/or function of the window. Lead-based paints were commonly used on older homes; independent inspection is required if confirmation or a risk assessment is desired.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Vegetation at House** - Planted or naturally growing vegetation (trees, shrubs and/or vines) is close to and/or in contact with the house exterior. This condition is conducive to infestation and damage from insects, organisms, and pests, including wood-destroying insects. Heavy vegetation can lead to retention of moisture, which in turn can lead to concerns with decay and mold. With near or direct contact with the building, surface damage is also possible. Signs of infestation and/or damage, if present, may be concealed by the vegetation. Recommend pruning or removing vegetation as necessary so there is adequate clearance around the house's exterior. Once clear, all surfaces should be inspected for damage and repaired as required.

(c) Copyright 2001-2008 DBR

Each HouseMaster Franchise is an Independently Owned and Operated Business.

### 3. SITE ELEMENTS

Inspection of site elements is primarily intended to address the condition of listed, readily visible and accessible elements immediately adjacent to or surrounding the house for conditions and issues that may have an impact on the house. Elements and areas concealed from view for any reason cannot be inspected. **Neither the inspection nor report includes any geological surveys, soil compaction surveys, ground testing, or evaluation of the effects of, or potential for, earth movement such as earthquakes, landslides, or sinking, rising or shifting for any reason.** Information on local soil conditions and issues should be obtained from local officials and/or a qualified specialist prior to closing. In addition to the stated limitations on the inspection of site elements, a standard home inspection does not include evaluation of elements such as underground drainage systems, site lighting, irrigation systems, barbecues, sheds, detached structures, fencing, privacy walls, docks, seawalls, pools, spas and other recreational items. Additional information related to site element conditions may be found under other headings in this report, including the FOUNDATION/SUBSTRUCTURE and WATER PENETRATION sections.

**PATIOS:**

Type: Masonry

Type: Brick/Pavers

Location: Rear of House

**WALKWAYS/DRIVEWAYS:**

Walks: Concrete

Walks: Brick/Pavers

Driveway: Concrete

S F P NA NI

•					3.0	PATIO(S)
•					3.1	WALKWAYS
	•				3.2	DRIVEWAY Cracking noted; recommend seal cracks.
	•				3.3	GROUND SLOPE AT FOUNDATION  A negative grade slope toward the foundation allows water runoff and ponding. This condition can causes structural and/or water infiltration problems. Excessive soil/water pressures can actually cause lateral movement of the foundation, a potentially serious concern. Deficiencies must be corrected and suitable drainage conditions must be maintained in order to prevent problems. Most notable deficiency occurs in the small alcove at the front of the house. Gutters are also needed here. (see Gutter comments in Roofing section)
•					3.4	SITE GRADING

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



3.2 DRIVEWAY Picture 1



3.3 GROUND SLOPE AT FOUNDATION Picture 1

**NOTE:** Site conditions are subject to sudden change with exposure to rain, wind, temperature changes, and other climatic factors. Roof drainage systems and site/foundation grading and drainage must be maintained to provide adequate water control. Improper/inadequate grading or drainage and other soil/site factors can cause or contribute to foundation movement or failure, water infiltration into the house interior, and/or mold concerns. Independent evaluation by an engineer or soils specialist is required to evaluate geological or soil-related concerns. Houses built on expansive clays or uncompacted fill, on hillsides, along bodies of water, or in low-lying areas are especially prone to structural concerns. All improved surfaces such as patios, walks, and driveways must also be maintained to drain water away from the foundation. Any reported or subsequently occurring deficiencies must be investigated and corrected to prevent recurring or escalating problems. Independent evaluation of ancillary and site elements by qualified service companies is recommended prior to closing.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Grading Provisions** - To reduce the amount of water run-off or ponding and potential for water penetration and/or structural concerns, a positive slope away from the foundation should be provided around the perimeter of the house. Maintenance of a suitable ground cover is also advised. Depressions or negatively graded areas should be corrected/improved to help direct any roof or surface run-off away from the foundation. The periodic addition of new fill soil and regrading may be required, especially with new homes. A negative grade slope can cause structural and/or water infiltration problems. Excessive soil/water pressures can actually cause lateral movement of the foundation, a potentially serious concern. Deficiencies must be corrected and suitable drainage conditions must be maintained in order to prevent problems.

## 4. GARAGE

Inspection of the garage is limited to readily visible and accessible elements as listed herein. Elements and areas concealed from view cannot be inspected. More so than most other areas of a house, **garages tend to be filled with storage and other items that restrict visibility and hide potential concerns, such as water damage or insect infestation.** A standard home inspection does not include an evaluation of the adequacy of the fire separation assemblies between the house and garage, or whether such assemblies comply with any specific requirements. Inspection of garage doors with connected automatic door operator is limited to a check of operation utilizing hard-wired controls only. Additional information related to garage elements and conditions may be found under other headings in this report, including ROOFS and EXTERIOR ELEMENTS.

### GARAGE DESCRIPTION:

Type: Attached  
 Type: Three Car  
 Type: Carport  
 Construction: Wood Frame

### GARAGE ATTIC:

Insp. Method: From Entrance  
 Est. Average: 6 to 8 Inches

### HOUSE/GARAGE WALL:

Finish at House: Drywall on Wall  
 Hard board/fiber board siding

### SPECIAL LIMITATIONS:

Storage/Belongings

S F P NA NI

		•			4.0	<b>ROOFING</b> See comments in Roofing section
			•		4.1	<b>EXPOSED FRAMING</b>
	•				4.2	<b>FLOOR SLAB</b> Cracking and settlement of floor slab noted; recommend seal cracks.
•					4.3	<b>ATTIC VENTILATION</b>
•					4.4	<b>WALLS / CEILINGS</b>
•					4.5	<b>SIDING</b>
•					4.6	<b>VEHICLE DOOR(S)</b>
•					4.7	<b>DOOR OPERATOR(S)</b>
	•				4.8	<b>ELECTRIC / GFCI</b> The outlet for the garage door opener is missing an outlet cover. Replace.

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



4.2 FLOOR SLAB Picture 1

**NOTE:** Any areas obstructed at the time of inspection should be cleared and checked prior to closing. The integrity of the fire-separation wall/ceiling assemblies generally required between the house and garage, including any house-to-garage doors and attic hatches, must be maintained for proper protection. Review manufacturer use and safety instructions for garage doors and automatic door operators. All doors and door operators should be tested and serviced on a regular basis to prevent personal injury or equipment damage. Any malfunctioning doors or door operators should be repaired prior to using. Door operators without auto-reverse capabilities should be repaired or upgraded for safety. The storage of combustibles in a garage creates a potential hazard, including the possible ignition of vapors, and should be restricted.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Limitations/Obstructions** - More than many other areas of a house, garages tend to contain storage and other items that restrict the ability to observe the structure and other components. Any noted limitation may be in addition to normal restrictions. Recommend all obstructed areas be inspected when clear.

## 5. ATTIC

The inspection of attic areas and the roof structure is limited to readily visible and accessible elements as listed herein. Due to typical design and accessibility constraints such as insulation, storage, finished attic surfaces, roofing products, etc., **many elements and areas, including major structural components, are often at least partially concealed from view and cannot be inspected.** A standard home inspection does not include an evaluation of the adequacy of the roof structure to support any load, the thermal value or energy efficiency of insulation, the integrity of vapor retarders, or the operation of thermostatically controlled fans. Older homes generally do not meet insulation and energy conservation standards required for new homes. Additional information related to attic elements and conditions may be found under other headings in this report, including ROOFS and INTERIOR ELEMENTS.

### ATTIC:

Style: Multiple Areas  
 Style: Exposed Framing  
 Entrance: Pull-Down Stairs  
 Insp. Method: Limited Entry

### ROOF CONSTRUCTION:

Framing: Wood Rafter  
 Deck: OSB Sheathing

### INSULATION:

Form: Blown-in  
 Est. Average: 6 to 8 Inches  
 Vapor Retarder: Not Observed

### VENTILATION PROVISIONS:

Location: Ridge and Soffits

### SPECIAL LIMITATIONS:

Storage/Belongings  
 No Flooring  
 Insulation Over Faming

S F P NA NI

•					5.0	<b>ROOF FRAMING</b>
		•			5.1	<b>ROOF DECK / SHEATHING</b> Home owner indicates storm damaged sheathing will be replaced before closing. (see Roofing Comments) Verify before closing.
•					5.2	<b>VENTILATION PROVISIONS</b>
•					5.3	<b>INSULATION</b>
•					5.4	<b>ATTIC STAIRS</b>

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



5.1 ROOF DECK / SHEATHING Picture 1

**NOTE:** Attic heat, moisture levels, and ventilation conditions are subject to change. All attics should be monitored for any leakage, moisture buildup or other concerns. Detrimental conditions should be corrected and ventilation provisions should be improved where needed. Any comments on insulation levels and/or materials are for general information purposes only and were not verified. Some insulation products may contain or release potentially

hazardous or irritating materials--avoid disturbing. A complete check of the attic should be made prior to closing after non-permanent limitations/obstructions are removed. Any stains/leaks may be due to numerous factors; verification of the cause or status of all condition is not possible. Leakage can lead to mold concerns and structural damage. If concerns exist, recommend evaluation by a qualified roofer or the appropriate specialist.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Limitations/Obstructions** - Due to typical design/accessibility constraints (insulation, storage, etc.,) evaluation of attic areas, including structural components, is generally limited. Any specifically noted limitations/obstructions are intended to highlight limitations beyond the norm. A complete check of the attic should be made when non-permanent limitations are removed.

(c) Copyright 2001-2008 DBR

Each HouseMaster Franchise is an Independently Owned and Operated Business.

## 6(A). HALL BATHROOM

The inspection of bathrooms is limited to readily accessible and visible elements as listed herein. Bathrooms are high-use areas containing many elements subject to ongoing wear and periodic malfunction, particularly fixtures and other components associated with the plumbing system. Normal usage cannot be simulated during a standard home inspection. **Water flow and drainage evaluations are limited to a visual assessment of functional flow.** The function and watertightness of fixture overflows or other internal fixture components generally cannot be inspected. A standard home inspection does not include evaluation of ancillary items such as saunas or steam baths. Additional issues related to bathroom components may be found under other headings, including the PLUMBING SYSTEM.

**DESCRIPTION:**

Full Bath

**LOCATION:**

Hallway

**VENTILATOR(S):**

Combo Light/Exhaust Fan

S F P NA NI

•						6.0.A	SINK(S)
	•					6.1.A	TOILET  The tank components are worn/not working properly allowing water to continuously run driving up water bills. In many cases only minor repair/adjustment may be required. In other cases, replacement of tank components would be the best approach.
•						6.2.A	BATHTUB
•						6.3.A	STALL SHOWER
•						6.4.A	WALL TILE
•						6.5.A	SURROUND / ENCLOSURE
•						6.6.A	FLOOR(ING)
•						6.7.A	WALLS / CEILING
•						6.8.A	VENTILATOR
•						6.9.A	ELECTRIC / GFCI

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** Anticipate the possibility of leakage or other concerns developing with normal usage/aging or as concealed conditions are discovered with maintenance work or upon removal of carpeting, tile, shower enclosures, etc. The watertightness of all surfaces exposed to water must be maintained on a regular basis by caulking, grouting, or other means. Hot water represents a potential scalding hazard; hot water supply temperatures should be maintained at a suitable level. The water temperature at fixtures, especially for showering or bathing, generally will require additional tempering for personal comfort and safety. Due to the potential hazards associated with electric components located in bathroom areas, any identified concern should be addressed immediately. Ground-Fault Circuit-Interrupters (GFCIs) are recommended for all bathroom receptacle outlets.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Stall Showers** - The base of many stall showers is a composite system, utilizing tile or other surface materials, with an underlying base (pan) of metal or other material. This type pan is not visible; the underside of other type shower bases are also not readily visible. Accordingly, it is not possible during a standard inspection to determine the watertightness of a shower pan. With normal aging/wear, leakage will eventually occur.

## 6(B). MASTER BATHROOM

The inspection of bathrooms is limited to readily accessible and visible elements as listed herein. Bathrooms are high-use areas containing many elements subject to ongoing wear and periodic malfunction, particularly fixtures and other components associated with the plumbing system. Normal usage cannot be simulated during a standard home inspection. **Water flow and drainage evaluations are limited to a visual assessment of functional flow.** The function and watertightness of fixture overflows or other internal fixture components generally cannot be inspected. A standard home inspection does not include evaluation of ancillary items such as saunas or steam baths. Additional issues related to bathroom components may be found under other headings, including the PLUMBING SYSTEM.

**DESCRIPTION:**

Master Bath

**LOCATION:**

Master Bedroom

**VENTILATOR(S):**

Combo Light/Exhaust Fan

S F P NA NI

•					6.0.B	SINK(S)
•					6.1.B	TOILET
•					6.2.B	STALL SHOWER
•					6.3.B	SURROUND / ENCLOSURE
•					6.4.B	FLOOR(ING)
•					6.5.B	WALLS / CEILING
•					6.6.B	VENTILATOR
•					6.7.B	ELECTRIC / GFCI
	•				6.8.B	JETTED BATH
<p>A limited check of the bathtub jets indicated there was water flow and aeration. A complete evaluation of the jetted bath system or its effectiveness was not performed. Recommend review of operational and maintenance procedures with the homeowner.</p> <p>Hot and cold facet handles on the tub (blue trim ring/red trim ring) are backwards from the hot and cold water sources. A simple switch of handles is recommended to avoid someone turning the wrong handle.</p>						

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



6.8.B JETTED BATH Picture 1

**NOTE:** Anticipate the possibility of leakage or other concerns developing with normal usage/aging or as concealed conditions are discovered with maintenance work or upon removal of carpeting, tile, shower enclosures, etc. The watertightness of all surfaces exposed to water must be maintained on a regular basis by caulking, grouting, or other means. Hot water represents a potential scalding hazard; hot water supply temperatures should be maintained at a suitable level. The water temperature at fixtures, especially for showering or bathing, generally will require additional tempering for personal comfort and safety. Due to the potential hazards associated with electric components located in bathroom areas, any identified concern should be addressed immediately. Ground-Fault Circuit-Interrupters (GFCIs) are recommended for all bathroom receptacle outlets.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Ventilator Discharge** - The bathroom exhaust fan should discharge directly to the exterior to prevent excess moisture concerns in the house or attic area. Recommend adding an extension to a suitable discharge point or correcting the current arrangement as conditions warrant.

## 6(C). HALF BATHROOM

The inspection of bathrooms is limited to readily accessible and visible elements as listed herein. Bathrooms are high-use areas containing many elements subject to ongoing wear and periodic malfunction, particularly fixtures and other components associated with the plumbing system. Normal usage cannot be simulated during a standard home inspection. **Water flow and drainage evaluations are limited to a visual assessment of functional flow.** The function and watertightness of fixture overflows or other internal fixture components generally cannot be inspected. A standard home inspection does not include evaluation of ancillary items such as saunas or steam baths. Additional issues related to bathroom components may be found under other headings, including the PLUMBING SYSTEM.

**DESCRIPTION:**

Half Bath

**LOCATION:**

Near Laundry Room

**VENTILATOR(S):**

Combo Light/Exhaust Fan

S F P NA NI

•					6.0.C	SINK(S)
		•			6.1.C	TOILET Toilet is loose at the floor; check for leakage/damage and secure as required.
•					6.2.C	FLOOR(ING)
•					6.3.C	WALLS / CEILING
		•			6.4.C	VENTILATOR  The bathroom exhaust fan should discharge directly to the exterior to prevent excess moisture concerns in the house or attic area. The exhaust fan duct in the attic is torn in half therefore venting directly into the attic. Recommend repairing/replacing the exhaust duct extension to the original discharge point.
•					6.5.C	ELECTRIC / GFCI

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



6.4.C VENTILATOR Picture 1

**NOTE:** Anticipate the possibility of leakage or other concerns developing with normal usage/aging or as concealed conditions are discovered with maintenance work or upon removal of carpeting, tile, shower enclosures, etc. The watertightness of all surfaces exposed to water must be maintained on a regular basis by caulking, grouting, or other means. Hot water represents a potential scalding hazard; hot water supply temperatures should be maintained at a suitable level. The water temperature at fixtures, especially for showering or bathing, generally will require additional tempering for personal comfort and safety. Due to the potential hazards associated with electric components located in bathroom areas, any identified concern should be addressed immediately. Ground-Fault Circuit-Interrupters (GFCIs) are recommended for all bathroom receptacle outlets.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Toilet Seal/Tank** - A loose toilet or defective seal can result in leakage and significant consequential damage and should be attended to as soon as possible. Seepage at the base of the toilet requires immediate attention. Floor, flooring, and/or other damage may be uncovered when the toilet is lifted for repair. Have checked and corrected as required.

**Ventilator Discharge** - The bathroom exhaust fan should discharge directly to the exterior to prevent excess moisture concerns in the house or attic area. Recommend adding an extension to a suitable discharge point or correcting the current arrangement as conditions warrant.

(c) Copyright 2001-2008 DBR

Each HouseMaster Franchise is an Independently Owned and Operated Business.

## 7. KITCHEN

Inspection of the kitchen is limited to visible and readily accessible elements as listed herein. Elements concealed from view or not functional at the time of inspection cannot be inspected. The inspection of cabinetry is limited to functional unit conditions based on a representative sampling; finishes and hardware issues are not included. **The inspection of appliances, if performed, is limited to a check of the operation of a basic representative cycle or mode** and excludes evaluation of thermostatic controls, timing devices, energy efficiency considerations, cooking or cleaning adequacies, self-cleaning functions, the adequacy of any utility connections, compliance with manufacturer installation instructions, appliance accessories, and full appliance features (i.e., all cycles, modes, and controls). Portable appliances or accessories such as washer, dryers, refrigerators, microwaves, and ice makers are generally excluded. Additional information related to kitchen elements and appliances may be found under other headings in this report.

**LOCATION:**

Main Kitchen

**WALL OVEN:**

Electric Oven  
w/ Built-in Microwave  
Est. Age: 6 to 8 Years

**DISHWASHER:**

Est. Age: 6 to 8 Years

**GARBAGE DISPOSAL:**

Est. Age: 6 to 8 Years

**VENTILATOR:**

Exhaust Fan

**SPECIAL LIMITATIONS:**

Storage/Obstructions

**REFRIGERATOR:**

Est. Age: 6 to 8 Years

**S F P NA NI**

	•					7.0	<b>PLUMBING / SINK</b> The cabinet area is obstructed with excessive storage. There appears to be stains of an old leak. No leak was occurring at time and date of inspection. Inspect after storage items removed and before closing for damage.
•						7.1	<b>FLOOR</b>
•						7.2	<b>WALLS / CEILING</b>
•						7.3	<b>ELECTRIC / GFCI</b>
•						7.4	<b>COOKTOP</b>
•						7.5	<b>OVEN</b>
	•					7.6	<b>DISHWASHER</b> Dish washer discharge line does not use a sink top vent. The dishwasher drain line connects directly to the garbage disposal. When no sink top vent is present, dishwasher drain line should form a loop to prevent waste back flow into the dishwasher. This presents the possibility to contaminate the clean water supply in the home. There may be a installation or drainage issue. Have checked prior to closing.
		•				7.7	<b>DISPOSAL</b> Disposal made excessive noise when operated; recommend repair or replace.
•						7.8	<b>VENTILATOR</b>
•						7.9	<b>CABINETS</b>
•						7.10	<b>COUNTERTOP</b>

**S F P NA NI**

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected


Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.



7.0 PLUMBING / SINK Picture 1



7.6 DISHWASHER Picture 1



7.6 DISHWASHER Picture 2

**NOTE:** Many appliances typically have a high maintenance requirement and limited service life (5-12 years). Operation of all appliances should be confirmed during a pre-closing inspection. Obtain all operating instructions from the owner or manufacturer; have the homeowner demonstrate operation, if possible. Follow manufacturers' use and maintenance guidelines; periodically check all units for leakage or other malfunctions. All cabinetry/ countertops should also be checked prior to closing when clear of obstructions. Utility provisions and connections, including water, waste, gas, and/or electric may require upgrading with new appliances, especially when a larger or upper-end appliance is installed. Ground-Fault Circuit-Interrupters (GFCIs) are recommended safety devices for all homes. Any water leakage or operational defects should be addressed promptly; water leakage can lead to mold and hidden/structural damage.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Dishwashers** - Any assessment of an installed dishwasher is limited to a single cycle operation of the motor/pump and visual check of readily accessible components. Dishwashing/cleaning adequacy and soap dispenser function were not evaluated. This is a high maintenance item. Seal leaks may develop after vacancy or other inactive periods.

## 8. INTERIOR ELEMENTS

Inspection of the house interior is limited to readily accessible and visible elements as listed herein. **Elements and areas that are inaccessible or concealed from view by any means cannot be inspected.** Aesthetic and cosmetic factors (e.g., paint and wallpaper) and the condition of finish materials and coverings are not addressed. Window and door evaluations are based on a random sampling of representative units. It is not possible to confirm safety glazing or the efficiency and integrity of insulated window/door units. Auxiliary items such as security/safety systems (or the need for same), home entertainment or communication systems, structured wiring systems, doorbells, telephone lines, central vacuums, and similar components are not included in a standard home inspection. Due to typical design restrictions, inspection of any fireplace, stove, or insert is limited to external conditions. Furthermore, such inspection addresses physical condition only; no code/fire safety compliance assessment or operational check of vent conditions is performed. Additional information on interior elements may be provided under other headings in this report, including the FOUNDATION/SUBSTRUCTURE section and the major house systems.

**PREDOMINANT WALLS & CEILINGS:**

Wood Frame w/ Drywall

**PREDOMINANT FLOORS:**

Concrete Slab  
w/ Carpeting  
w/ Tile  
w/ Wood or Wood Laminate

**PREDOMINANT WINDOWS:**

w/Insulated Glass  
w/Screens

**FIREPLACES/STOVES:**

Metal Fireplace w/ Gas Burner  
In Living Room

**DETECTORS:**

Location: Hallway/Sleeping Area  
Type: Hard-Wired  
Type: Smoke/Fire Detection

**SPECIAL LIMITATIONS:**

Excess Furnishing/Storage  
Belongings/Clutter

S F P NA NI

•					8.0	CEILINGS
•					8.1	WALLS
•					8.2	FLOORS (SLAB)
•					8.3	WINDOWS
•					8.4	ROOM DOORS
•					8.5	FIREPLACE
				•	8.6	FIREPLACE GAS BURNERS Gas logs/burners were not evaluated. Manual ignition required.

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** All homes are subject to indoor air quality concerns due to factors such as venting system defects, outgassing from construction materials, smoking, and the use of house and personal care products. Air quality can also be adversely affected by the growth of molds, fungi and other micro-organisms as a result of leakage or high humidity conditions. If water leakage or moisture-related problems exist, potentially harmful contaminants may be present. A home inspection does not include assessment of potential health or environmental contaminants or allergens. For air quality evaluations, a qualified testing firm should be contacted. All homes experience some form of settlement due to construction practices, materials used, and other factors. A pre-closing check of all windows, doors, and rooms when house is clear of furnishings, drapes, etc. is recommended. If the type of flooring or other finish materials that may be covered by finished surfaces or other items is a concern, conditions should be confirmed before closing. Lead-based paint may have been used in the painting of older homes. Chimney and fireplace flue inspections should be performed by a qualified specialist. Regular cleaning is recommended. An assessment should be made of the need for and placement of detectors. All smoke and carbon monoxide detectors should be tested on a regular basis.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Security/Safety Systems** - A standard home inspection does not include evaluation of the adequacy of any existing security or safety system or the need for one. Each owner should perform his/her own assessment of the systems that may be desired or required, or arrange to have a qualified specialist perform such an evaluation.



## 9. ELECTRIC SYSTEM

The inspection of the electric system is limited to readily visible and accessible elements as listed herein. Wiring and other components concealed from view for any reason cannot be inspected. **The identification of inherent material defects or latent conditions is not possible. The description of wiring and other components and the operational testing of electric devices and fixtures are based on a limited/random check of representative components.** Accordingly, it is not possible to identify every possible wiring material/type or all conditions and concerns that may be present. Inspection of Ground-Fault Circuit-Interrupters (GFCIs) is limited to the built-in test functions. No assessment can be made of electric loads, system requirements or adequacy, circuit distribution, or accuracy of circuit labeling. Auxiliary items and electric elements (or the need for same) such as surge protectors, lighting protection systems, generators, security/safety systems, home entertainment and communication systems, structured wiring systems, low-voltage wiring, and site lighting are not included in a standard home inspection. Additional information related to electric elements may be found under many other headings in this report.

### HOUSE SERVICE:

Service Line: Underground  
 Est. Service Capacity: 120/240 Volts; 200 Amps  
 Type Service Feeder: Copper  
 Est. Feeder Capacity: 200 Amps

### DISTRIBUTION PANEL:

Type: Circuit Breaker Panel  
 w/ Subpanel  
 Est. Capacity: 200 Amps  
 Disconnect: Multiple Disconnects  
 Location: Exterior

### PANEL CIRCUITS:

120 Volt Circuits: Copper Wire  
 240 Volt Circuits: Copper Wire

### SUBPANEL:

Type: Circuit Breaker Panel  
 Est. Capacity: 100 Amps  
 Disconnect: 100 Amps  
 Location: Utility Room

### CIRCUIT-INTERRUPTERS:

GFCI: At Receptacle Outlets  
 AFCI: None Observed

S F P NA NI

•					9.0 SERVICE / ENTRANCE LINE
•					9.1 SERVICE GROUNDING PROVISIONS
•					9.2 MAIN DISCONNECT(S)
•					9.3 DISTRIBUTION PANEL
•					9.4 SUBPANEL(S)
•					9.5 DEVICES
•					9.6 WIRING / CONDUCTORS
•					9.7 GFCI TEST

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** Older electric service may be minimally sufficient or inadequate for present/future needs. Service line clearance from trees and other objects must be maintained to minimize the chance of storm damage and service disruption. The identification of inherent electric panel defects or latent conditions is not possible. It is generally recommended that aluminum-wiring systems be checked by an electrician to confirm acceptability of all connections and to determine if any remedial measures are required. GFCIs are recommended for all high hazard areas (e.g., kitchens, bathrooms, garages and exteriors). AFCIs are relatively new devices now required on certain circuits in new homes. Consideration should be given to adding these devices in existing homes. The regular testing of GFCIs and AFCIs using the built-in test function is recommended. Recommend tracing and labeling of all circuits, or confirm current labeling is correct. Any electric defects or capacity or distribution concerns should be evaluated and/or corrected by a licensed electrician.

### **SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Auxiliary/Low Voltage Systems** - Evaluation of ancillary, low voltage electric or electronic equipment (e.g., TV, doorbell, computer, cable, lightning protection, surge protection, low voltage lighting, intercoms, site lighting, alarms etc.) is not performed as part of a standard home inspection.





## 11. HEATING SYSTEM

The inspection of heating systems is limited to readily visible and accessible elements as listed herein. Elements concealed from view or not functional at the time of inspection for any reason cannot be inspected. **A standard home inspection does not include a heat-loss analysis, heating design or adequacy evaluation, energy efficiency assessment, installation compliance check, chimney flue inspection or draft test, solar system inspection, or buried fuel tank inspection.** Furthermore, portable units and system accessories or add-on components such as electronic air cleaners, humidifiers, and water treatment systems are not inspected, unless specifically indicated. The functional check of heating systems is limited to the operation of a basic cycle or mode and excludes the evaluation of thermostatic controls, timing devices, analysis of distribution system flow or temperatures, or operation of full system features (i.e., all cycles, modes, and controls). Additional information related to the heating system may be found under other headings in this report, including the COOLING SYSTEM section.

**TYPE SYSTEM:**

Natural Gas

**BRAND:**

Rheem

**SYSTEM LOCATION:**

Attic

**ESTIMATED AGE:**

6 to 8 Years

**GENERAL DISTRIBUTION:**

Ducted w/Registers

**S F P NA NI**

•						11.0	<b>HEATING UNIT</b> Ambient air test was performed by using thermometers on air handler of the furnace to determine if the difference in temperature through the heat exchanger was within normal operational levels. The supply air temperature read 113 degrees, and the return air temperature was 75 degrees. This indicates that the unit is working within typical temperature range. System is 8 years old. It is recommended the system be inspected and serviced by a qualified HVAC technician.
•						11.1	<b>BURNER</b>
•						11.2	<b>FUEL LINE AT UNIT</b>
		•				11.3	<b>VENT CONNECTOR</b> Vent connector flashing is loose causing potential for roof leaks. Verify replacement with roof replacement. See comments in Roofing section.
•						11.4	<b>BLOWER</b>
•						11.5	<b>DISTRIBUTION SYSTEM</b>
•						11.6	<b>THERMOSTAT</b>

**S F P NA NI**

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** Regular heating system maintenance is important. The older the unit the greater the probability of system deficiencies or failure. Combustion air provisions, clearances to combustibles, and venting system integrity must be maintained for safe operation. Any actual or potential concerns require immediate attention, as health and safety hazards may exist, including the potential for carbon monoxide poisoning. A thorough inspection of heat exchangers by a qualified heating specialist is recommended to determine heat exchanger conditions, particularly if the unit is beyond 5+ years old or any wear is indicated. Heating comfort will vary throughout most houses due to house or system design or other factors. Filters need to be replaced/cleaned on a regular basis; periodic duct cleaning may be required. Insulation on older heating systems may contain asbestos. Independent evaluation is required to address any possible asbestos or buried fuel tank concerns. Servicing or repair of heating systems should be made by a qualified specialist.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Maintenance/Service** - Servicing or repair of the heating system normally must be done by a qualified service company; most utility companies only service/handle gas supply concerns.

## 12. PLUMBING SYSTEM

The inspection of the plumbing system is limited to readily visible and accessible elements as listed herein. Piping and other components concealed from view for any reason cannot be inspected. Material descriptions are based on a limited/random check of representative components. Accordingly, **it is not possible to identify every piping or plumbing system material, or all conditions or concerns that may be present.** A standard home inspection does not include verification of the type water supply or waste disposal, analysis of water supply quantity or quality, inspection of private onsite water supply or sewage (waster disposal) systems, assessment/analysis of lead piping/solder or lead-in-water concerns, or a leakage test of gas/fuel piping or storage systems. Furthermore, the function and effectiveness of any shut-off/control valves, water filtration or treatment equipment, irrigation/fire sprinkler systems, outdoor/underground piping, backflow preventers (anti-siphon devices), laundry standpipes, vent pipes, floor drains, fixture overflows, and similar features generally are not evaluated. Additional information related to plumbing elements may be found under other headings in this report, including BATHROOMS and KITCHEN.

**WATER SUPPLY PIPING:**

Copper

**DRAIN/WASTE LINES:**

Plastic (PVC/ABS)

**LOCATION OF SHUT-OFFS:**

Water: At Meter

Water: At Front of House

Gas: At Meter

Gas: At Left Side of House

**SPECIAL LIMITATIONS:**

Nearly 100% Concealed Piping

S F P NA NI

•						12.0	WATER SUPPLY PIPING
•						12.1	WATER FLOW AT FIXTURES
•						12.2	DRAIN / WASTE PIPING
•						12.3	FIXTURE DRAINAGE
•						12.4	EXTERIOR FAUCET(S)
•						12.5	GAS PIPING

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** Recommend obtaining documentation/verification on the type water supply and waste disposal systems. If private onsite water and/or sewage systems are reported/determined to exist, independent evaluation (including water analyses) is recommended. Plumbing systems are subject to unpredictable change, particularly as they age (e.g., leaks may develop, water flow may drop, or drains may become blocked). Plumbing system leakage can cause or contribute to mold and/or structural concerns. Some piping may be subject to premature failure due to inherent material deficiencies or water quality problems, (e.g., polybutylene pipe may leak at joints, copper water pipe may corrode due to acidic water, or old galvanized pipe may clog due to water mineral content). Periodic cleaning of drain lines, including underground pipes will be necessary. Periodic water analyses are recommended to determine if water filtration and treatment systems are needed. Confirm and label gas and water shut-off valve locations. A qualified plumber should perform all plumbing system repairs.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Concealed Plumbing** - Due to building/unit design, aside from plumbing fixtures visible within the dwelling, all plumbing system components are concealed and therefore could not be inspected.

**Water Supply/Flow** - While the adequacy of water flow (volume/pressure) may be subjective, observed flows are less than would normally be expected. There are a number of potential causes, including water supply, piping and/or plumbing fixtures concerns. Further assessment by a qualified plumber will be required to determine if and what type remedial action is warranted.

## 13. HOT WATER SUPPLY

The inspection of hot water supply systems is limited to readily visible and accessible elements as listed herein. Elements concealed from view for any reason cannot be inspected. All standard water heaters require temperature-pressure relief valves (TPRV); these units are not operated during a standard home inspection but should be checked regularly for proper operation. **A standard home inspection does not include evaluation of the adequacy/capacity of hot water supply systems, or inspection of saunas, steam baths, or solar systems.** An increase in the hot water supply system capacity may be needed for large jetted baths or other fixtures requiring a large volume of hot water, or when bathroom or plumbing facilities are added or upgraded. Additional information related to the hot water supply system may be found under other headings in this report, including the BATHROOMS and PLUMBING SYSTEM sections.

**HOT WATER SUPPLY:**

Tank-type Unit

**ENERGY SOURCE/FUEL:**

Gas

**ESTIMATED AGE:**

6 to 8 Years

**BRAND:**

A.O. Smith

**ESTIMATED CAPACITY:**

50 +/- Gallons

**LOCATION:**

Attic

S F P NA NI

•						<b>13.0 WATER HEATER</b>	The hot water supply temperature is well above normal safe use levels and there is a high potential for scalding or other injury. Recommend correcting for safety.
		•				<b>13.1 VENT CONNECTOR</b>	Vent connector flashing is loose causing potential for roof leaks. Verify replacement with roof replacement. See comments in Roofing section.
•						<b>13.2 GAS / FUEL LINES AT UNIT</b>	
•						<b>13.3 SAFETY VALVE PROVISIONS</b>	

S F P NA NI

S=Satisfactory, F=Fair, P=Poor, NA=Not Applicable, NI=Not Inspected

Review REPORT TERMINOLOGY on Introduction Page. Consult with your Inspector for clarification on ratings or findings if there are any questions.

**NOTE:** Maintaining hot-water supply temperatures at no more than about 120°F (49°C) will reduce the risk of injury; hot water represents a potential scalding hazard. Anti-scald devices are available as an added safety measure. The combustion chamber or ignition sources of water heaters and other mechanical equipment in garage areas should be positioned/maintained at least 18 inches above the floor for safety reasons. Adequate clearance to combustibles must also be maintained around the unit and any vents. Restraining straps are generally required on heaters in active seismic zones. Safety valve (TPRV) discharge should be through a drain line to a readily visible area that can be monitored. Newer tanks should be drained periodically, but many old tanks are best left alone. Tankless or boiler coils systems have little or no storage capacity; a supplemental storage tank can often be added if needed. A qualified plumber or specialist should perform all water heating system repairs.

**SUPPLEMENTAL INFORMATION - Review the additional details below.**

**Domestic Hot Water** - The adequacy of the domestic hot water supply or temperatures was not determined. Evaluations are limited to assessment of visual conditions and confirmation of heated water flow to the fixtures. Newer tanks should be drained periodically, but many old tanks are best left alone.

## SUMMARY OF INSPECTOR COMMENTS

This Summary of Inspector Comments is only one section of the Inspection Report and is provided for guidance purposes only. This Summary is **NOT A HOME INSPECTION REPORT** and does not include information on all conditions or concerns associated with this home or property. **The Inspection Report** includes more detailed information on element ratings/conditions and associated information and **must be read and considered in its entirety prior to making any conclusive purchase decisions or taking any other action**. Any questionable issues should be discussed with the Inspector and/or Inspection Company.

**Note:** While listings in this Summary of Inspector Comments may serve as a guide to help prioritize remedial needs, the final decision regarding any action to be taken must be made by the client following consultation with the appropriate specialists or contractors.

## 1. ROOFING

### 1.0 ROOF COVERING

**Poor**

The roof conditions observed might be indicative of roof wear, hail or storm damage, manufacturing defects, and/or other conditions. Home owner advises they are awaiting storm damage insurance claim and roof will be replaced before closing. Follow up and verify reroofing was complete before closing. Obtain copies of receipts and warranties.



1.0 Picture 1



1.0 Picture 2

### 1.1 EXPOSED FLASHING

**Poor**

Damaged flashing observed in several areas. Verify flashing deficiencies are corrected with roof replacement as indicated in the Roof Covering comments.



1.1 Picture 1

### 1.2 PLUMBING STACKS

**Fair**

Poor seal noted around plumbing vent stack at rear of home verify replacement with roof replacement. See comments in roofing section.

### 1.3 VENTILATION COVERS

**Fair**

Dryer exhaust vent terminates on rear roof. The vent has heavy lint accumulation. Verify cleaning or replacement with roof replacement. See comments in roofing section/

## 1. ROOFING

### 1.4 RAIN GUTTERS / EAVESTROUGHS

#### Fair

No gutters are present at the small alcove in the front of the house. (see comments in Site Elements) This is contributing to water ponding. It is recommended gutters be installed here. Home owner indicates gutters will be replaced at site of roof damage (see comment in Roof Covering) with roof replacement. Verify before closing.

### 1.6 FASCIA / SOFFITS

#### Poor

Soft/fascia damaged sheathing noted at along edge of roof; home owner indicates this will be replaced during reroofing. (see Roof Covering comments) Verify work completion before closing.



1.6 Picture 1

## 2. EXTERIOR ELEMENTS

### 2.2 ENTRY DOORS

#### Fair

Main entry door has paint bubbles on the interior. This may be cosmetic but also shows signs of possible water penetration. Sand and repaint to avoid wood rot or insect infestation.



2.2 Picture 1

### 3. SITE ELEMENTS

#### 3.2 DRIVEWAY

Fair

Cracking noted; recommend seal cracks.



3.2 Picture 1

#### 3.3 GROUND SLOPE AT FOUNDATION

Fair

A negative grade slope toward the foundation allows water runoff and ponding. This condition can cause structural and/or water infiltration problems. Excessive soil/water pressures can actually cause lateral movement of the foundation, a potentially serious concern. Deficiencies must be corrected and suitable drainage conditions must be maintained in order to prevent problems. Most notable deficiency occurs in the small alcove at the front of the house. Gutters are also needed here. (see Gutter comments in Roofing section)



3.3 Picture 1

## 4. GARAGE

### 4.0 ROOFING

**Poor**

See comments in Roofing section

### 4.2 FLOOR SLAB

**Fair**

Cracking and settlement of floor slab noted; recommend seal cracks.



4.2 Picture 1

### 4.8 ELECTRIC / GFCI

**Fair**

The outlet for the garage door opener is missing an outlet cover. Replace.

## 5. ATTIC

### 5.1 ROOF DECK / SHEATHING

**Poor**

Home owner indicates storm damaged sheathing will be replaced before closing. (see Roofing Comments) Verify before closing.



5.1 Picture 1

## 6(A). HALL BATHROOM

### 6.1.A TOILET

Fair

The tank components are worn/not working properly allowing water to continuously run driving up water bills. In many cases only minor repair/adjustment may be required. In other cases, replacement of tank components would be the best approach.

## 6(B). MASTER BATHROOM

### 6.8.B JETTED BATH

Fair

A limited check of the bathtub jets indicated there was water flow and aeration. A complete evaluation of the jetted bath system or its effectiveness was not performed. Recommend review of operational and maintenance procedures with the homeowner.

Hot and cold facet handles on the tub (blue trim ring/red trim ring) are backwards from the hot and cold water sources. A simple switch of handles is recommended to avoid someone turning the wrong handle.



6.8.B Picture 1

## 6(C). HALF BATHROOM

### 6.1.C TOILET

Poor

Toilet is loose at the floor; check for leakage/damage and secure as required.

### 6.4.C VENTILATOR

Poor

The bathroom exhaust fan should discharge directly to the exterior to prevent excess moisture concerns in the house or attic area. The exhaust fan duct in the attic is torn in half therefore venting directly into the attic. Recommend repairing/replacing the exhaust duct extension to the original discharge point.



6.4.C Picture 1

## 7. KITCHEN

### 7.0 PLUMBING / SINK

**Fair**

The cabinet area is obstructed with excessive storage. There appears to be stains of an old leak. No leak was occurring at time and date of inspection. Inspect after storage items removed and before closing for damage.



7.0 Picture 1


### 7.6 DISHWASHER

**Fair**

Dish washer discharge line does not use a sink top vent. The dishwasher drain line connects directly to the garbage disposal. When no sink top vent is present, dishwasher drain line should form a loop to prevent waste back flow into the dishwasher. This presents the possibility to contaminate the clean water supply in the home. There may be an installation or drainage issue. Have checked prior to closing.



7.6 Picture 1



7.6 Picture 2

### 7.7 DISPOSAL

**Poor**

Disposal made excessive noise when operated; recommend repair or replace.

## 8. INTERIOR ELEMENTS

### 8.6 FIREPLACE GAS BURNERS

**Not Inspected**

Gas logs/burners were not evaluated. Manual ignition required.

## 11. HEATING SYSTEM

### 11.3 VENT CONNECTOR

**Poor**

Vent connector flashing is loose causing potential for roof leaks. Verify replacement with roof replacement. See comments in Roofing section.

## 13. HOT WATER SUPPLY

### 13.0 WATER HEATER

**Fair**

The hot water supply temperature is well above normal safe use levels and there is a high potential for scalding or other injury. Recommend correcting for safety.

### 13.1 VENT CONNECTOR

**Poor**

Vent connector flashing is loose causing potential for roof leaks. Verify replacement with roof replacement. See comments in Roofing section.

(c) Copyright 2001-2008 DBR

Each HouseMaster Franchise is an Independently Owned and Operated Business.

Prepared Using HomeGauge 4 <http://www.HomeGauge 4.com> SHGI (c) 2000-2009 : Licensed To Pro2Call Property Evaluations LLC dba HouseMaster