



# Office of Pest Management

## WOOD-DESTROYING INSECT INSPECTION REPORT

THIS IS NOT A STRUCTURAL DAMAGE FUNGI/MOLD REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD-DESTROYING INSECTS. CONSIDER ASSESSMENT BY A LICENSED STRUCTURAL CONTRACTOR OR FUNGI/MOLD INSPECTOR FOR ANY STRUCTURAL DAMAGE OR FUNGI/MOLD CONCERN.

1A. VA/HUD/FHA CASE #	DATE OF INSPECTION Day Month Year
1B. <input checked="" type="checkbox"/> ORIGINAL REPORT <input type="checkbox"/> SUPPLEMENTAL REPORT	1D. WDIR # S09xxxxx-xH
1C. PURPOSE OF REPORT <input checked="" type="checkbox"/> Sale <input type="checkbox"/> Refinancing <input type="checkbox"/> Other	1E. TARF #

NOTE: Pursuant to: ARS§32-3321 (B) (1) (10), ARS§32-2324 (A) This form must be completed only by an Active Licensed Applicator or Qualifying Party.

### 2. READ CAREFULLY PRIOR TO COMPLETING THIS OFFICE OF PEST MANAGEMENT (OPM) FORM

- The VA or HUD/FHA case number shall be inserted in Item 1A by the lender or by the pest control company.
- Areas that were inaccessible or obstructed (Item 7) may include, but are not limited to, wall coverings, fixed ceilings, floor coverings, furniture, or stored articles. In Item 7, the Inspector shall list those obstructions or areas which inhibited the inspection.
- Item 8A alone is checked when evidence/insects are found but no control measures are performed. Items 8A and 8C are checked when evidence/insects are found AND control measures are performed.
- When visible evidence is observed, wood-destroying insects causing such evidence shall be listed in Item 8A and the visible damage resulting from such infestation shall be noted in Item 8D.
- When treatment is indicated in Item 8C, the insects treated shall be named and the date of treatment indicated. The application method and chemicals used shall be entered in Item 10. Proper control measures may include issuance of a warranty. Warranty information shall also be entered in Item 10. (Proper control measures are those which are allowed by OPM Statute/Rule, or the label for the chemical used).
- Visible evidence of conditions conducive to infestation from wood-destroying insects shall be reported in Items 15-18 on the second page of this form, (e.g., earth-wood contact, faulty grade, insufficient ventilation, etc.).
- All supplemental reports shall be completed within (30) days of the date of the original report.

3A. NAME OF INSPECTION COMPANY <b>HouseMaster Home And Termite Inspections</b>	5A. NAME OF PROPERTY OWNER/SELLER <b>Property Owner</b>
3B. ADDRESS OF INSPECTION COMPANY (Street, City, ZIP) <b>3030 S Rural Rd STE 109 Tempe AZ 85282</b>	5B. PROPERTY ADDRESS (Street, City, ZIP) <b>Property street and city</b>
3C. TELEPHONE NUMBER (Include Area Code) <b>480-345-8570</b>	4. BUSINESS LICENSE # <b>8360</b>
6A. INSPECTED STRUCTURES <b>Structure Inspected</b>	

6B. LIST ALL UN-INSPECTED STRUCTURES  
**Structures Not Inspected**

7. THIS INSPECTION DOES NOT INCLUDE THE FOLLOWING LISTED AREAS WHICH ARE OBSTRUCTED OR INACCESSIBLE. (See also Item 19, page 2.)

### 8. BASED ON THE INSPECTOR'S VISUAL INSPECTION OF THE READILY ACCESSIBLE AREAS OF THE PROPERTY (See Section (11) before completing):

- A. Visible evidence of wood-destroying insects was observed.  
Describe evidence observed: Evidence  
Type of Wood-Destroying Insects observed: Insect observed
- B. No visible evidence of infestation from wood-destroying insects was observed.
- C. Visible evidence of infestation as noted in 8A. Proper control measures were performed on (date): \_\_\_\_\_
- D. Visible damage due to **Moisture, Rot or insects** was observed in the following areas: \_\_\_\_\_  
**location of damage**
- E. Visible evidence of previous treatment was observed. List evidence. (See also Item 20, page 2.): Drill holes and location of treatment

9. DAMAGE OBSERVED, IF ANY <input type="checkbox"/> A. Will be or has been corrected by this company. <input type="checkbox"/> B. Will not be corrected by this company. <input type="checkbox"/> C. It is recommended that noted damage be evaluated by a licensed structural contractor for any necessary repairs to be made.	10. ADDITIONAL COMMENTS (ALSO SEE PAGE 2.)  (Number of additional attachments to this report.) _____ Page(s)
--	--

11. STATEMENT OF INSPECTOR
- The inspection covered the readily accessible areas of the above listed structures, including attics and crawl spaces which permitted entry.
  - Special attention was given to those areas which experience has shown to be particularly susceptible to attack by wood-destroying insects.
  - Non-destructive probing and/or sounding of those areas and other visible accessible wood members showing evidence of infestation was performed.
  - The inspection did not include areas which were obstructed or inaccessible at the time of inspection.
  - Neither I, nor the company for which I am acting, have had, presently have, or contemplate having any interest in this property. I do further state that neither I, nor the company for which I am acting, is associated in any way with any party to this transaction.

12A. SIGNATURE OF INSPECTOR <i>Harold J. Kerner</i>	12B. INSPECTOR'S LICENSE NUMBER 011165	12C. DATE Day Month Year
--	---	-----------------------------

ADDITIONAL INFORMATION REGARDING TERMITE TREATMENTS AND/OR INSPECTIONS OF THIS PROPERTY MAY BE AVAILABLE FROM THE OFFICE OF PEST MANAGEMENT (OPM) 9535 E. Doubletree Ranch Road, Scottsdale, Arizona 85258-5514 (602) 255-3664 - (602) 255-1281 fax http://www.sb.state.az.us

### STATEMENT OF PURCHASER

I HAVE RECEIVED THE ORIGINAL, OR A LEGIBLE COPY, OF THIS FORM AND HAVE READ PAGE (1, 2, 3) OF THIS FORM.

13. SIGNATURE OF PURCHASER	14. DATE
----------------------------	----------

<b>PROPERTY NAME/ADDRESS</b> <b>Property street and address</b>	<b>DATE OF INSPECTION</b> <b>Day Month Year</b>
--	--

**AT THE TIME OF THE INSPECTION THE PROPERTY WAS:**       Vacant       Occupied       Unfurnished       Furnished

CONDITIONS CONDUCTIVE TO INFESTATION

**15. WOOD TO EARTH CONTACT (EC)**       YES     NO    *(If YES, check mark and explain conditions conducive)*

- |   |                                       |  |
|---|---------------------------------------|--|
| <input type="checkbox"/> Fence Abutting Structure | <input type="checkbox"/> Pier Posts   | <input type="checkbox"/> Plantings/Planters Contacting Structure |
| <input type="checkbox"/> Concrete Form Boards     | <input type="checkbox"/> Porch Stairs | <input type="checkbox"/> Other _____                             |
| <input type="checkbox"/> Porch Post               | <input type="checkbox"/> Trellis      |  |

Comments: **Location of EC**

**16. EXCESSIVE CELLULOSE DEBRIS (CD)**       YES     NO    *(If YES, check mark and explain conditions conducive)*

Comments: **Location of CD**

**17. FAULTY GRADES (FG)**       YES     NO    *(If YES, check mark and explain conditions conducive)*

- |   |  |
|---|--|
| <input type="checkbox"/> Slope; surface water tends to drain toward house | <input type="checkbox"/> Stucco at or below grade                        |
| <input type="checkbox"/> Floor level at or below grade                    | <input type="checkbox"/> Joists in crawl space less than 18" above grade |
| <input type="checkbox"/> Wood siding below grade                          | <input type="checkbox"/> Other _____                                     |

Comments: \_\_\_\_\_

**18. EXCESSIVE MOISTURE (EM)**       YES     NO    *(If YES, check mark and explain conditions conducive)*

- |   |   |   |   |
|---|---|---|---|
| <input type="checkbox"/> Standing Water               | <input type="checkbox"/> Water Damage                 | <input type="checkbox"/> Bath/Shower/Toilet Leaking | <input type="checkbox"/> Inadequate Ventilation |
| <input type="checkbox"/> Sprinklers Hitting Structure | <input type="checkbox"/> Water Stain                  | <input type="checkbox"/> Plumbing Leaks             | <input type="checkbox"/> Other _____            |
| <input type="checkbox"/> Crawl Space/Water Leaking    | <input type="checkbox"/> Improper Condensate Drainage | <input type="checkbox"/> Attic/Roof Leak            |   |

Comments: **Location of EM and description**

**19. INACCESSIBLE AREAS (IA)**       YES     NO    *(If YES, check mark and explain conditions conducive)*

- |  |  |   |
|--|--|---|
| <input type="checkbox"/> Attic – All               | <input checked="" type="checkbox"/> Floors         | <input type="checkbox"/> Sub/Crawl Space Area -- Clearance                |
| <input type="checkbox"/> Attic – Joists            | <input checked="" type="checkbox"/> Wall Interiors | <input type="checkbox"/> Sub Area/Crawl Space No Access                   |
| <input type="checkbox"/> Attic – Partial           | <input type="checkbox"/> Enclosed Stairwell        | <input type="checkbox"/> Areas Obstructed By Furniture Or Stored Articles |
| <input checked="" type="checkbox"/> Plumbing Trans | <input type="checkbox"/> Dropped Ceilings          | <input type="checkbox"/> Other _____                                      |

Comments: **Design and Insulatoin limit access**

**Garage, cabinets and closets due to storage**

**Most rooms have rooms that are covered or obstructed by furniture and/or stored items**

**The House is vacant occupied**

**20. EVIDENCE OF PREVIOUS TREATMENT**

- BY ANOTHER COMPANY:** While evidence of previous treatment does exist, it is impossible for the inspecting company to ascertain if such treatment was properly performed. Further investigation is left to the Buyer's discretion to determine if such treatment was done properly and if a valid warranty exists against the target pest of such treatment.
- BY THE INSPECTING COMPANY:** Previous treatment is recorded for this property. At the Buyer's discretion, treatment records can be viewed at the inspecting company's local office with the property owner's permission.


Account Number: \_\_\_\_\_ Date of Initial Treatment: \_\_\_\_\_ Target Pest: \_\_\_\_\_

Warranty Expiration Date: \_\_\_\_\_ Other: \_\_\_\_\_

Pest	Control	Inspector's	Additional	Comments:

# GRAPH OF STRUCTURE(S)

(Note: Graph Not To Scale)



**PURSUANT TO: R4-29307 (E)(1) THROUGH (5) & (a) THROUGH (p) THE INSPECTOR MUST COMPLETE THE GRAPH ON PAGE (3) FOR ANY NOTED ITEMS WHICH ARE CHECK (✓) MARKED BELOW**

✓	CODE	SEE GRAPH PAGE (3)	✓	CODE	SEE GRAPH PAGE (3)	✓	CODE	SEE GRAPH PAGE (3)	✓	CODE	SEE GRAPH PAGE (3)
	SU	Subterranean Termites		OW	Other Wood Destroying Insects (*)		OB	Obstructions		WD	Water Damage
	DR	Drywood Termites		FG	Faulty Grade	<input checked="" type="checkbox"/>	IA	Inaccessible Areas		WS	Water Stains
	DA	Dampwood Termites		EC	Wood To Earth Contact		IV	Inadequate Ventilation		RL	Roof Leaks
	BE	Wood Destroying Beetles		CD	Cellulose Debris		PL	Plumbing Leaks		EM	Excessive Moisture
	CA	Carpenter Ants		PA	Plantings Abutting Structure		SP	Sprinkler Hitting Structure		FI	Further Inspection Needed
	(*) Other Wood Destroying Insects										